



GARY R. HERBERT
Governor

GREGORY S. BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining
JOHN R. BAZA
Division Director

Minerals Inspection Report

Reviewed PTW

Report Date: 04/23/2014

Mine Name: ML 47821&46956/Cubical2	Permit Number: S/023/0057	Mine Status: Active
Operator Name: Mike Sprunger	Inspection Date: 04/09/2014	Permit Fees: Paid
Inspector(s): Wayne Western - Duane Bays	Inspection Time: 12:01 PM - 2:40 PM	Bond Amount: \$5,400
Attendee(s): Mike Sprunger	Weather: Warm and partly cloudy	Bond Escalation: 12/13/2009
Inspection Purpose: Operator request		Prior Inspection: 08/10/2011

Conclusions and Recommendations


The Operator needs to increase the bond. After the inspection, the Operator agreed to increase the bond to \$8,300.00

Elements of Inspection	Evaluated & Commented	Enforcement
1. Permits, Revisions, Transfer, Bonds The bond is \$5,400.00 and needed to be increased to \$8,300.00. Letter asking for additional bond sent.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls) There are no shafts or adits at the sites. The public collects mineral specimens in and around the site. There are no safety issues noted during inspection.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages/Erosion Control No sign of erosion problems at the sites	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety) BLM will determine is road to the northern site should be included in the NOI	<input checked="" type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts)	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>
10. Other	<input type="checkbox"/>	<input type="checkbox"/>

Inspector's Signature: Wayne Western

CC:

File: /nrwogmfs1/OGM/GROUPS/MINERALS/WP/M023-Juab/S0230057-Sprunger-3sites/Inspections/INSP04092014.pdf



Southern site 39 N 41 ' 48.89" 113 W 05' 52.47"



Looking west at northern end of disturbed area on SITLA ground



Looking west at southern end of disturbed area



Overview of disturbed area



Middle site 39 N 46' 39.90" 113 W 05' 44.28"




Waste piles



Waste piles



Active area



Northern site 39 N 50' 24.79" 113 W 07' 09.75"



Waste piles



Entrance to site



Disturbed area